Welcome To

1003 Weldin Circle Weldin Woods















Welcome to this six-bedroom, three-and-a-half-bath brick colonial in the heart of North Wilmington. This home has a traditional floor plan with hardwood floors throughout. From the moment you step inside, the freshly painted entry, living, dining, and kitchen areas offer a warm and inviting atmosphere. The oversized formal living and dining rooms flank the entrance, providing a perfect setting for hosting gatherings with family and friends. Both rooms have ample windows allowing abundant natural light to fill the spaces. The adjacent, cozy family room with a wood stove insert and brick accent wall opens to a three-season room with three walls of windows. This flex space can be an office, yoga retreat, or a peaceful spot for reading or morning coffee. The heart of this home is undoubtedly the eat-in kitchen, which features wrap-around cabinets and counter space, making meal preparation a breeze. The laundry and half bath are conveniently located on the way to the rear attached garage. The sixth bedroom/in-law suite with an attached full bath completes the main floor. Upstairs, the primary suite is a true retreat, boasting two large closets, a nursery/ office, a separate built-in vanity, and a private bathroom. Four additional generously sized bedrooms share a well-appointed hall bath. Beyond the size and conveniences of the home itself, its location is simply unbeatable. The North Wilmington location offers easy access to major commuter routes. Nearby attractions, such as the Can-Do playground, Alapocas Run State Park, Bellevue State Park, Rockwood Park & Museum, and the Brandywine Zoo, ensure that there's always something exciting to explore. Nemours Children's Hospital is also nearby. Don't miss your opportunity to make this remarkable house your forever home. Notable features: Fresh paint throughout, HEPA Filter attached to the A/C unit, large basement with sump pump, and plenty of built-in storage shelves and closets.



Patterson-Schwartz Real Estate
Melissa Goode Spencer
Team Landon
302-256-1552 direct
302-733-7000 office
mspencer@psre.com





PROPERTY DESCRIPTION

Coming Soon



\$615,000

1003 Weldin Circle, Wilmington, DE, 19803

 MLS #:
 DENC2067532
 Beds:
 6

 Type:
 Residential
 Baths:
 3 / 1

Struct Type: Detached YearBuilt: 1972 / Estimated

Style:ColonialNewConstr:NoLvls/Stories:2Basement:YesOwnership:Fee SimpleCentral Air:Yes

Garage: Yes

OpenHouse: Sun, Sep 8, 1:00PM-4:00PM

LOCATION

County: **NEW CASTLE** School District: Brandywine MLS Area: Brandywine (30901) High School: Brandywine Subdiv/Neigh: Weldin Woods Middle School: Springer In City Limits: Ν Elementary School: Lombardy

ASSOCIATION / COMMUNITY INFO

Senior Community: No HOA: No Condo/Coop: No

TAXES AND ASSESSMENT

Tax ID#: 06-112.00-1339 Tax Annual/Year: \$6,300 / 2023 Tax Assessment: \$178,100

ROOMS					BED	BATH
Living Room:	Main	19 x 15	Crown Molding, Flooring - HardWood	Main:	1	1 full 1 part
Kitchen:	Main	17 x 19	Flooring - Tile/Brick, Kitchen - Eat-in,	Upper 1:	5	2 full
	Pantry					
Dining Room:	Main	18 x 13	Crown Molding, Flooring - HardWood			
Family Room:	Main	20 x 13	Fireplace - Wood Burning, Flooring -			
	HardWood,	Wood Stove				
Laundry:	Main	9 x 8	Flooring - Tile/Brick			
Primary Bedroom:	Upper 1	21 x 18	Flooring - HardWood			
Bedroom 2:	Upper 1	21 x 10	Flooring - HardWood			
Bedroom 3:	Upper 1	16 x 14	Flooring - HardWood			
Bedroom 4:	Upper 1	17 x 15	Flooring - HardWood			
Bedroom 5:	Upper 1	14 x 11	Flooring - HardWood			
Bedroom 6:	Main	13 x 11	Attached Bathroom, Flooring -			
	HardWood					
Recreation Room:	Lower 1	28 x 23				

BUILDING INFORMATION

AboveGrFinSF: 3,475 / Assessor BelowGrFinSF: 644 / Estimated BelowGrFinSF: 644 / Estimated Total Finished SF: 4,119 / Total SF: 4,119 / Foundation: Block, Crawl Space Basement: Crawl Space, Partially Finished Constr Materials: Brick, Vinyl Siding Flooring Type: Hardwood, Slate, Tile/Brick

LOT AND PARKING

Lot Acres/SQFT: 0.38a / 16,553sf / Estimated Zoning: NC15 Federal Flood Zone: No Parking: Attached Garage, Driveway | Paved Parking | Garage - Front Entry, Garage Door Opener | Attached Garage Spaces: 2 | Driveway Spaces: 2

INTERIOR FEATURES

Crown Moldings, Formal/Separate Dining Room, Kitchen - Eat-In, Pantry, Stove - Wood, Wood Floors | Fireplace(s): 1, Brick, Insert, Wood | Cooktop, Dishwasher, Dryer, Oven - Double, Oven - Wall, Oven/Range - Gas, Water Heater | Laundry: Main Floor | Accessibility Features: None

EXTERIOR FEATURES

Exterior Lighting

UTILITIES

Cooling: Central A/C, Electric | Heating: Forced Air, Natural Gas | Electric: 200+ Amp Service, Circuit Breakers | Hot Water: Natural Gas | Water Source: Public | Sewer: Public Sewer

REMARKS

Expected On Market Date: September 5, 2024

Public: Welcome to this six-bedroom, three-and-a-half-bath brick colonial in the heart of North Wilmington. This home has a traditional floor plan with hardwood floors throughout. From the moment you step inside, the freshly painted entry, living, dining, and kitchen areas offer a warm and inviting atmosphere. The oversized formal living and dining rooms flank the entrance, providing a perfect setting for hosting gatherings with family and friends. Both rooms have ample windows allowing abundant natural light to fill the spaces. The adjacent, cozy family room with a wood stove insert and brick accent wall opens to a three-season room with three walls of windows. This flex space can be an office, yoga retreat, or a peaceful spot for reading or morning coffee. The heart of this home is undoubtedly the eat-in kitchen, which features wrap-around cabinets and counter space, making meal preparation a breeze. The laundry and half bath are conveniently located on the way to the rear attached garage. The sixth bedroom/in-law suite with an attached full bath completes the main floor. Upstairs, the primary suite is a true retreat, boasting two large closets, a nursery/office, a separate built-in vanity, and a private bathroom. Four additional generously sized bedrooms share a well-appointed hall bath. Beyond the size and conveniences of the home itself, its location is simply unbeatable. The North Wilmington location offers easy access to major commuter routes. Nearby attractions, such as the Can-Do playground, Alapocas Run State Park, Bellevue State Park, Rockwood Park & Museum, and the Brandywine Zoo, ensure that there's always something exciting to explore. Nemours Children's Hospital is also nearby. Don't miss your opportunity to make this remarkable house your forever home. Notable features: Fresh paint throughout, HEPA Filter attached to the A/C unit, large basement with sump pump, and plenty of built-in storage shelves and closets.

Exclusions: Standing lamps, Egg Grill, Desk lamps in living room



For More Information Contact:

Melissa Goode Spencer

Team Landon Cell: 302-256-1552

Office: 302-733-7000 e-mail: mspencer@psre.com

www.teamlandon.com

1003 Weldin Circle

1003 Weldin Circle, Wilmington



Front Porch



Foyer



Living Room



Living Room



Kitchen

Kitchen

1003 Weldin Circle, Wilmington



Dining Room



Family Room



Main Level Bedroom



Full Bath on Main Level



3 Season Room

3 Season Room





Powder Room



Laundry



Primary Bedroom



Office or Closet in Primary Bedroom



Bedroom

1003 Weldin Circle, Wilmington



Bedroom



Bedroom



Bedroom



Full Bath



Sun Room Addition



Basement

1003 Weldin Circle, Wilmington



Rear of home

BASEMENT 224° x 285° BASEMENT 184° x 285°

TOTAL: 4398 sq., ft
Below Ground: 773 sq. ft, PLOOR 2: 1902 sq. ft, PLOOR 3: 1723 sq. ft
EXCLUDED AREAS: BASEMENT: 469 sq. ft, UNDEFINIO: 31 sq. ft, GARAGE: 442 sq. ft
PORCH: 138 sq. ft



TOTAL: 4396 sq. ft.
Below Ground: 773 sq. ft., FLOOR 2: 1902 sq. ft, FLOOR 3: 1723 sq. ft
EXCLUDED AREAS: BASEMENT: 489 sq. ft, LOPEPINIO: 31 sq. ft, GARAGE: 442 sq. ft,
PORCH: 136 sq. ft

Yard



TOTAL: 4399 sq. ft
Below Ground: 773 sq. ft, FLOOR 2: 1902 sq. ft, FLOOR 3: 1723 sq. ft
EXCLUDED AREAS: BASEMENT: 489 sq. ft, UNDEFINED: 31 sq. ft, GARAGE: 442 sq. ft
PORCH: 138 sq. ft

PROFESSIONAL REGULATION OF MERSIA TOP

Purchased: Built to own 1972

SELLER'S DISCLOSURE OF REAL PROPERTY CONDITION REPORT

State of Delaware

Approved by the Delaware Real Estate Commission (Effective Date: July 1, 2023)

Seller(s) Name: Marc and Mavis Woolley 1003 Weldin Circle Wilmington, DE 19803

Property Address: Approximate Age of Building(s): ___52 years ______ Date

property property must be for any the time This Re the Sell warrant materia was ma materia Coordin https://do	y that a y mean a made mater a the Export is a ror a lies that I defend the mation direct.	are kn ar	6 of the Delaware Code, requires a Seller of residential property to disclose in writing all material defects of the nown at the time the property is offered for sale or that are known prior to the time of final settlement. Residential y interest in a property or manufactured housing lot, improved by dwelling units for 1-4 families. The disclosure his Report, which has been approved by the Delaware Real Estate Commission and shall be updated as necessary ranges occurring in the property before final settlement. This Report shall be given to all prospective Buyers prior to makes an offer to purchase. This Report, signed by Buyer and Seller, shall become a part of the Agreement of Sale. Food faith effort by the Seller to make the disclosures required by Delaware law and is not a warranty of any kind by regents or Sub-Agents representing Seller or Buyer in the transfer and is not a substitute for any inspections or Seller or Buyer may wish to obtain. The Buyer has no cause of action against the Seller or Real Estate Agent for the property disclosed to the Buyer prior to the Buyer making an offer; material defects developed after the offer losed in an update of this Report prior to settlement, provided Seller has complied with the Agreement of Sale; or hich occur after settlement. Government websites containing helpful information include: Office of State Planning to May the report of Seller Planning Report Real Report Planning Report Planning Report Real Report Planning Report Planning Report Real Report Planning Re
Yes	No	*	* Write in U if Unknown or NA if Not Applicable, otherwise mark either the Yes or No column. Where selections are requested, place a check mark next to each correct answer or fill in the correct answer. Certain answers require a further explanation in Section XVI. Seller shall answer the following questions based on Seller's knowledge of the property.
			I. OCCUPANCY
Burnel.	X		How do you currently use this property? As a: (_X_Primary Residence) (Second/Vacation Home) (_ Rental Property) (Other:). If not your Primary Residence, how long has it been since you occupied the property?approximately 2 months
	х		2. Is the property encumbered by arental/lease), (option to purchase), or (first right of refusal)? If yes, describe in XVI. Seller agrees to provide a copy of the rental/lease agreement to Buyer upon request.
		N A	3. If the property is a rental/lease, have all necessary permits and/or licenses been obtained?
		N A	4. If the property is a rental/lease, is the property subject to a rental/lease management agreement?
S		N A	5. If #4 is yes, is the agreement binding upon the purchaser? If yes, describe in XVI. Seller agrees to provide a copy of the management agreement to Buyer upon request.

	X		6. Is the property new construction?
	D	N A	7. If #6 is yes, has a certificate of occupancy been issued? If yes, when? If no, STOP USING THIS FORM and complete the Seller's Disclosure of Real Property Condition Report New Construction Only.
		Tank de constant de la constant de l	erty Address:1003 Weldin Circle Wilmington, DE Water
		_ Sell	er's Initials Seller's Initials Buyer's Initials Buyer's Initials
Yes	No	*	* Write in <i>U</i> if Unknown or <i>NA</i> if Not Applicable, otherwise mark either the Yes or No column. Where selections are requested, place a check mark next to each correct answer or fill in the correct answer. Certain answers require a further explanation in Section XVI. Seller shall answer the following questions based on Seller's knowledge of the property.
NA			8. If #6 is yes, Seller warrants that the property (is) or (is not) exempt from providing the Buyer with a Public Offering Statement as described in §81-401 or §81-403(b) of Chapter 81, Title 25 of the Delaware Code, The Delaware Uniform Common Interest Ownership Act. If exempt from providing the Public Offering Statement or Resale Certificate, in compliance with §317A of Chapter 3, Title 25, Seller has attached a copy of all documents in the chain of title that create any financial obligation for the buyer, and a written summary of all financial obligations created by documents in the chain of title. As evidenced by signature below, Buyer has received a copy of these documents.
			II. DEED RESTRICTIONS, HOMEOWNERS ASSOCIATIONS / CONDOMINIUMS AND CO-OPS
Ø	X		9. Is the property subject to any deed restrictions? (e.g., rent al restrictions, pet restrictions, fence requirements, etc.) If yes, describe in XVI.
壓	X		10. Are you in violation of any deed restrictions at this time? If yes, describe in XVI.
	Х		11. Is the property subject to any agreements concerning affordable housing or workforce/inclusionary housing? If yes, describe in XVI.
©	X		12. Is the property subject to any private, public, or historic architectural review control other than building codes? If yes, describe in XVI.
<u>F</u>	X		13. Is the property part of a condominium or cooperative (Co-op) ownership?
2	X		14. Is there a (Homeowners Association), (Condominium Association), (Cooperative (Co-op),
	E	N A	15. If #14 is yes, are there any (Fees), (Dues), or (Assessments) involved?
	5	N A	16. Is there a capital contribution fee due by a new owner to the Association? If yes, how much

	X		17. Are there any unpaid assessments including but not limited to deferred water and sewer charges for your property? If yes, how much? If yes, describe in XVI.
	X		18. Has there been a special assessment in the past 12 months? If yes, describe in XVI.
	X		19. Have you received written notice of any new, proposed, or board discussed increases in fees, dues, assessments, or capital contributions? If yes, describe in XVI.
		N A	20. Management Company Name:
		N A	21. Representative Name: Phone #
		N A	22. Representative E-mail Address:
			III. TITLE / ZONING INFORMATION
固	79	N A	23. Does the amount owed on your mortgage(s) and any other lien(s) exceed the estimated value of the property? If yes, are additional funds available from Seller for settlement?
		N	24. Is your property owned (In fee simple) or (Leasehold/Ground Lease) or (Cooperative)?
		N A	25. If a Leasehold/Ground Lease, what is the current lease amount? \$; Frequency of payments: (Weekly), (Monthly), (Quarterly), (Yearly), (Other:)
		N A	26. If a Leasehold/Ground Lease, when does it expire?
		U	27. Are there any rights-of-way, easements, or similar matters that affect the property? If yes, describe in XVI.
	X		28. Are there any shared maintenance agreements affecting the property? If yes, describe in XVI.
	X		29. Are there any variance, zoning, conditional use, non-conforming use, or setback violations? If yes , describe in XVI.
da		N A	30. If #29 is yes, has the variance, conditional use, or non-conforming use expired or has otherwise become non-transferable? If yes, describe in XVI.
	X		31. Is your property currently covered by a title insurance policy?
	X		32. Did you participate in any mortgage/closing cost assistance program that must be paid back at the time of the transfer of the property? If yes, describe in XVI.
3	X		33. Did you participate in any mortgage forbearance programs such as the CARES Act from COVID-19? If yes, describe in XVI.
- Consumo			

Page 2 of 9 Property Address: _1003 Weldin Circle

Seller's	s Initia		MAW Seller's Initials MLWntw er's Initials Seller's Initials	Buyer's InitialsBuyer's Initials	
		- T			
Yes	No	*	* Write in U if Unknown or NA if Not Applicable, are requested, place a check mark next to each con require a further explanation in Section XVI. Seller shall answer the following questions based o	rrect answer or fill in the correct	answer. Certain answers
	100000		IV. ADDITIONAL INFORMATION		
Z	X		34. Have you received notice from any local, sta corrections of any existing conditions? If yes, d		repairs, alterations, or
屋	X		35. Is there any existing legal action affecting th	is property? If yes, describe in	XVI.
8	X		36. Are there any violations of local, state or fed describe in XVI.	eral laws or regulations relating	g to this property? If yes,
193	X		37. Does your current real estate tax amount refl	ect any non-transferrable exem	ptions or discounts? If

38. Have you received formal notice of any changes that may materially or adversely affect the property? e.g., zoning changes, road changes, proposed utility changes, etc. If yes to any, describe in XVI.

41. During your ownership, are there now or have there been animals (pets) living in the house? If yes, what

42. Is there now or has there ever been a (Swimming pool), (Hot tub), (Spa), or (Whirlpool) on

39. Are all the exterior door locks in the house in working condition? If no, describe in XVI.

the 🖺 🖫 🗀 property? If yes and there are any defects, describe in XVI.

Community) or 🖾 🖾 🖾 (__Other _____). 🗇

installation, replacement, repair, and snow removal.

V. ENVIRONMENTAL CONCERNS

The property owner(s), estimated fees: \$ Delaware Department of Transportation or the State of Delaware

43. If there is a pool, does it conform to all local ordinances? If no, describe in XVI.

44. What is the type of trash disposal? (X_Private), (__Municipal), (__County), (__

45. The cost of repairing and repaving the streets adjacent to the property is paid for by:

46. Is off street parking available for this property? If yes, number of spaces available: _

Note to Buyer: Repairing and repaving of the streets can be very costly. (6 Delaware Code§ 2578)

Note to Buyer: Please check HOA/local requirements concerning responsibility for sidewalk

yes, describe in XVI.

type? Dogs

Municipal Community/HOA

X Unknown

Other

40. Will keys be provided for each lock?

X

X

X

X

U

X

X

図 N

4

X

A

X			47. Are there now or have there been any underground storage tanks on the property? (Heating fuel), [X_ Propane), (Septic), or (Other:). [Septic Se
國	B		48. If the tank was abandoned, was it done with all necessary permits and properly abandoned?
		U	49. Are asbestos-containing materials present? If yes, describe in XVI.
2		U	50. Are there any lead hazards? (e.g., lead paint, lead pipes, lead in soil.) If yes, describe in XVI.
			51. Has the property been tested for toxic or hazardous substances? If yes, describe in XVI and provide the test results.
	X		52. Has the property ever been tested for mold? If yes, provide the test results.
M	X		53. Has the illegal manufacture, storage, or use of methamphetamines occurred in the property? If yes, describe in XVI.
	X		54. Is there a wastewater spray irrigation system (human or agricultural) installed on or adjacent to the property
	<u> </u>		VI. LAND (SOILS, DRAINAGE, AND BOUNDARIES)
	X		55. Is there fill soil or other fill material on the property?
3		U	56. Are there sliding, settling, earth movement, upheaval, earth stability, or methane gas release problems that have occurred on the property or in the immediate neighborhood? If yes, describe in XVI.
	X		57. Is any part of the property located in (a flood zone) and/or (a wetlands area)?
	X		58. Are there drainage or flood problems affecting the property? If yes, describe in XVI.
	X		59. Do you carry flood insurance? Agent: Policy #
		N A	60. If #59 is yes, what is the annual cost of this policy?
<u> </u>	固		Note to Buyer: Public and/or private flood insurance options exist for most properties regardless if property is located in a flood zone. Inquire about options with a qualified insurance agent.
ge 3	of 9	Рторе	erty Address:1003 Weldin Cicle
er's	Initia	ls	MAWSeller's InitialsMLW_MUBuyer's InitialsBuyer's Initials
		Selle	er's Initials Buyer's Initials Buyer's Initials Buyer's Initials
/es	No	*	* Write in <i>U</i> if Unknown or <i>NA</i> if Not Applicable, otherwise mark either the Yes or No column. Where selections are requested, place a check mark next to each correct answer or fill in the correct answer. Certain answers require a further explanation in Section XVI. Seller shall answer the following questions based on Seller's knowledge of the property.

X	23		61. Have you made any insurance claims on the property in the past 5 years? If yes, describe in XVI.		
	X		62. Does the property have standing water in front, rear, or side yards for more than 48 hours after raining? If yes, describe in XVI.		
		U	63. Are there encroachments or boundary line disputes affecting the property? If yes, describe in XVI?		
	X		64. Are there any ditches crossing or bordering the property? If yes, describe in XVI.		
1351 1251	X		65. Are there any swales crossing the property that are under the control of a Soil and Conservation District? If yes, describe in XVI.		
X	回		66. Have you ever had the property surveyed?		
		U	67. Are the boundaries of the property marked in any way? If yes, describe in XVI.		
	1		VII. STRUCTURAL ITEMS		
图			68. Have you made any additions or structural changes? If yes, describe in XVI.		
X			69. If #68 is yes, was all work done with all necessary permits and approvals in compliance with building codes?		
		N A	70. If #69 is yes, are the permits closed?		
	X		71. Is there now or has there ever been any movement, shifting, or other problems with walls or foundations? If yes, describe in XVI.		
[2]	X		72. Has the property, or any improvements thereon, ever been damaged by (Fire), (Smoke), (Wind), or 🖾 🖾 (Flood)? 🗆 If yes, describe in XVI.		
	X		73. Was the structure moved to this site? (
X			74. Is there now or has there ever been any non-plumbing water leakage in the house? If yes, describe in XVI.		
X			75. Are there any problems with (Exterior walls), (X_Driveways), (Walkways), (Patios), [Porches] or (Retaining walls) on the property? [Porches] If yes, describe in XVI.		
X	83		76. Are there any problems with (Interior walls), (Ceilings), (X_Floors), or (X_Windows) on the 🖾 🖂 🖂 property? If yes, describe in XVI.		
X			77. Have there been any repairs or other attempts to control the cause or effect of problems described in questions 74, 75, and 76? If yes, describe in XVI.		
X			78. Is there insulation in the: (_X_Ceiling/attic), (_X_Exterior walls), (_Crawlspace/basement), or [
			VIII. TERMITES, INSECTS, AND WILDLIFE		
	X		79. Is there now or has there ever been any infestation by termites or other wood destroying insects? If yes, describe in XVI.		
X			80. During your ownership, have there been any termite or other wood destroying insect inspections made on the property? If yes, describe in XVI.		
3		U	81. Is there now or has there ever been any damage to the property caused by (

		in XVI.
X	图	82. Have there ever been any termite or wood destroying insect treatments made on the property? If yes, describe in XVI.
	X	83. Is there or has there ever been an infestation of insects? If yes, describe in XVI.
X	B	84. During your ownership, have there been any insect control inspections made on the property. If yes, describe in XVI.
X		85. Are you aware of any insect control treatments made on the property? If yes, describe in XVI.
8	X	86. Are there now or have there ever been any bat colonies present on the property? If yes, describe in XVI.
[2]	X	87. Is your property currently under warranty, or other coverage, by a professional pest control company? If yes, name of exterminating company:
- WAIN'S WITH THE		IX. BASEMENT AND CRAWL SPACES
X		88. Does the property have a sump pump? If yes, where does it drain? Sewer
X	M	89. Is there now or has there ever been any water leakage, accumulation, or dampness within the basement, crawlspace, or other interior areas of the structure? If yes, describe in XVI.
X	E	90. Have there been any repairs or other attempts to control any water or dampness problem in the basement, crawlspace, or other interior areas of the structure? If yes, describe in XVI.
团	X	91. Are there any cracks or bulges in the floors or foundation walls? If yes, describe in XVI.

Page 4	of 9	Prop	perty Address:	1003 Weldin Circle		
		noministrative				
Seller's	s Initia	ıls_l	MAW	Seller's Initials MLW MLW	Buyer's Initials	Buyer's Initials
	and the state of t			Seller's Initials		Buyer's Initials
Yes	No	*	are requested require a fur	if Unknown or <i>NA</i> if Not Applicable, d, place a check mark next to each conther explanation in Section XVI. Inswer the following questions based o	rrect answer or fill in the correct	t answer. Certain answers
			X. ROOF			
				roof surface installed: _4-5years age, explain in XVI.	0	. If all roof surfaces not
			93. How man	ny layers of roof material are there ((e.g., new shingles over old shi	ngles)?1
B	X		94. Are there	e any problems with the roof, flashing	ng, rain gutters, or skylights? It	f yes or repaired under

			your ownership, explain in XVI.
圝	X		95. If under warranty, is warranty transferable?
			96. Where do your gutters drain? (_X_Surface), (Drywell), (Storm Sewers), (Other:
			XI. PLUMBING-RELATED ITEMS
			97. What is the drinking water source? (Municipal), (County), (X_Public Utility), 🖾 🖾 (Private Well), (Other: 🗆 🗀)
			98. If drinking water is supplied by public utility, name of utility:City of Wilmington
	X		99. Is there a water treatment system? If yes, (Leased) or (Owned)? \[\square\$
		N A	100. If water source is a well, when was it installed? Location of well? Depth of well? If more than one well, describe in XVI.
			101. What type of plumbing is used for the Water Supply? (_X_Copper), (_ Lead), (_ Cast Iron), (_ PVC), SEG (_ PEX), (_ Polybutylene), (_ Galvanized), (_ Other/Unknown:) E
			102. What type of plumbing is used for Drainage? (Copper), (Lead), (X_ Cast Iron), (X_ PVC),
			103. Age of Water Heater?3 years Water heater type: (XTank), (Tankless), (Other: 🖾 🖾
			104. Water Heater Fuel: (Electric), (Oil), (Propane Gas), (X_ Natural Gas)
		U	105. Are there now or have there ever been any leaks, backups, or other problems relating to any of the plumbing, water, and sewage related items? If yes, describe in XVI. 106. Are there any additions and/or upgrades to the original service? If yes, describe in XVI.
			107. If #106 is yes, was the work done by a licensed contractor?
			108. If #106 is yes, were the required permits obtained?
	8		109. If #108 is yes, are the permits closed?
		N A	110. If your drinking water is from a well, when was your water last tested and what were the results of the test? Tested on: Results:
			111. What is the type of sewage system? (_X_Public Sewer), (Community Sewer), (Septic System),
		N A	112. If a septic system, type: (Gravity Fed), (Capping Fill), (LPP), (Mound),
		N A	113. If a septic system, when was it last pumped?
		N	114. If a septic system, has it been inspected by a Class H inspector within the last 36 months, as required

		A	by DNREC regulations? If yes, describe in XVI and provide the test results.
		N A	115. If a septic system, how many bedrooms is the septic permitted to service?
	Х		116. Are there any shut off, disconnected, or abandoned wells, underground water or sewer tanks on the property? If yes, describe locations in XVI.
國	2	N A	117. If #116 is yes, were they abandoned with all necessary permits and properly abandoned?
-x-4-9 11		1	XII. HEATING AND AIR CONDITIONING
			118. How many heating and/or air conditioning systems are on the property?1 If more than 2, explain in XVI.
			119. Type of heating system for system #1 (_X_Forced air), (_Heat pump), (_Mini-Split), (_Baseboard), (_Radiator), (_Other: _)
			120. Type of heating fuel for system #1 (Oil), (Propane Gas), (X_Natural Gas), (Electric),
		[West
ler's	Initia		AAW Seller's Initials MLW Buyer's Initials Buyer's Initials er's Initials Buyer's Initials Buyer's Initials Buyer's Initials
Yes	No	*	* Write in <i>U</i> if Unknown or <i>NA</i> if Not Applicable, otherwise mark either the Yes or No column. Where selections are requested, place a check mark next to each correct answer or fill in the correct answer. Certain answers require a further explanation in Section XVI. Seller shall answer the following questions based on Seller's knowledge of the property.
			121. Fuel provider for: Heating system #1DelMarVa Heating System #2:
			122. Age of furnace #1: 8yrs Date of last service: August 2023 Age of furnace #2: Date of last service:
	X		123. Are there any contractual obligations affecting the fuel supply, tanks, or system(s)? If yes, describe in 3
			124. Type of air conditioning for system #1 (X Central), (Window Units), (Mini-Split), [_] [_] (Other: [_]) Type of air conditioning for system #2 (Central), (Window Units), (Mini-Split),

	_		
			□ □ □ (Other: □)
E43	X		125. Are there any contractual obligations affecting the heating/air conditioning system(s)? If yes, describe in XVI.
			126. Age of air conditioning system #1:16years Date of last service:August 2023 Age of air conditioning system #2: Date of last service:
Х	8		127. Have there been any additions and/or upgrades to the original heating or air conditioning? If yes, describe in XVI.
X	圂		128. If #127 is yes, was the work done by a licensed contractor?
		U	129. If #127 is yes, were the required permits obtained?
1	8	U	130. If #129 is yes, are the permits closed?
E	X		131. Are there any problems with the heating or air conditioning systems? If yes, describe in XVI.
			XIII. ELECTRICAL SYSTEM
			132. Who is the electric provider for the property?DelMarVa
			133. What type of wiring is in the house? (copper, aluminum, other, etc.) Aluminum
		U	134. What is the amp service? (60), (100), (150), (200), (Other: _ 🖾 🖼 🖾
			135. Does the property have (_X_ Circuit Breakers) or (Fuses)? If more than one electrical panel, describe in XVI.
	团	U	136. Are there any 220/240 volt circuits? (Other:)
	Х		137. Do fuses blow or circuit breakers trip when two or more appliances are being used at the same time? If yes, describe in XVI.
E	X		138. Are there wall switches, light fixtures, or electrical outlets in need of repair? If yes, explain in XVI.
	X		139. Is there a permanently affixed generator on the property? What is the fuel source?
	图	U	140. Have there been any additions to the original service?
	X		141. Have any (solar) and/or (wind powered) enhancements been made to supplement service? If yes, describe in XVI. Name of solar company?; If leased, what is the term? Note to Buyer: Transfer of lease is subject to approval by: Buyer must register with the Public Service Commission.
	匿	N A	142. If #139, #140, or #141 is yes, was work done by a licensed electrician?
图	23	N A	143. If #139, #140, or #141 is yes, were the required permits obtained?
回		N A	144. If #143 is yes, is the permit closed?
	1	٠	XIV. FIREPLACE OR HEATING STOVE

			145. How many fireplaces and/or heating stoves are on the property?1 If more than 2, explain in XVI.
			146. Type of fuel for fireplace 1: (X_Wood Burning), (_Propane Gas), (_Natural Gas), BB (_Other:)? D Type of fuel for fireplace 2: (_W ood Burning), (_Propane Gas), (_Natural Gas), BB (_Other:)? D
			147. Type of fuel for heating stove 1: (_X_ Wood Burning), (Pellet), (Other:
X	区		148. Was the fireplace or heating stove part of the original house design?
X	3		149. Was the fireplace or heating stove installed by a professional contractor or manufacturer's representative?
図	X		150. Are there any problems? If yes, explain in XVI.
國		U	151. When were the flues/chimneys last cleaned, serviced, or repaired?Cleaned Explain nature of service or repair in XVI.
'age 6	of 9	Ртор	erty Address: _1003 Weldin Circle
			/
Seller's	s Initia		MAW Seller's Initials MLW Buyer's Initials Buyer's Initials er's Initials Buyer's Initials Buyer's Initials Buyer's Initials
<u>(V. M.</u> Are	AJOR	Sell API	

F			
Wo Wo Coo Xo Wo Wall Xo Wo Kitch Xo Wo Refri #Xo Wo Ice Xo Wo Disp Xo Wo Disp Xo Wo Drye Wo Drye Wo Wash Xo Wo Drye Wo Wo Wash Xo Wo Wo Wash Xo Wo O Drye Wo Wo Wo Wash Xo Wo Wo Wash Xo Wo Wo Wash Xo Wo Wo Wash	te Hood-exhaust fan oktop-stand alone Oven(s) # nen Refrigerator icemaker igerator(s)-additional o Freezer – free standing Maker-free standing washer iosal iowave iter ir ish Compactor iter Filter ir Heater ip Pump in Windows/Doors	Xo Oo Draperies/Curtains Co Oo Drapery/Curtain rods Xo Oo Shades/Blinds Oo Furnace Humidifier Xo Oo Smoke Detectors Oo Carbon Monoxide Detectors Xo Oo Wood Stove Xo Oo Fireplace Equipment Xo Oo Fireplace Screen/Doors Oo Electronic Air Filter Oo Window A/C Units #	
			owned) o Security/Monitoring Systems (owned) o Security/Monitoring Systems (leased) o Solar Equipment (owned) O Solar Equipment (leased)
Page 7 of 9 P	roperty Address:1003 V	Weldin Circle	
Seller's Initial	s MAW Seller's	InitialsMLW_MVWBuyer's In	pitials Buver's Initials
	Seller's Initials	Seller's Initials Buyer's	s Initials Buyer's Initials
XVI. ADDITI	ONAL INFORMATION		
If you were d sections I throneeded.	irected to this section to clar ough XV, provide an explan	rify an answer, or if you indicated the ation of your recollection using com	ere is a problem with any of the items in mon language. Attach additional sheets if
Questi on Numb er	Additional Information		
47	Propane tank was remov	ed in the 70s.	
61	Bathroom Repair(Powde	r room and upstairs green bathroo	om) Water damage State Farm

8	The screened porch was converted to a three season room. Public record does not reflect the finished basement. Permits will not be obtained.
4	Basement had water leaking in and a sump pump was installed.
5	Driveway Right side near garage door: Tree roots, tree was cut down
6	Floor in kitchen slopes. Some windows don't lock or stay open.
7	Some settling cracks were repaired in drywall. A limb fell on the old roof which caused a few minor leaks. This has been repaired with no further issues
0	Carpenter ants outside in a dead tree
2, 84, 85	Terminex for prevention
9	Water leaking in from the ground was fixed with a sump pump. French drain installed underground on the side yard, and brick surround was created around basement window. The front hose bib was decommissioned due to leaking.
0	A sump pump inside and an outside french drain system to the left of the house
06	Replaced cast iron drainage pipe from kitchen with PVC
22	Both replaced with new units
	The electrical meter on the side of the house is detached from the siding.
	The built-in ladder to the attic needs repair.

	e there additional problem, clarified Number of Sheets Attached	Secretarian San Co.	rached? _X_No Ye	·S.
Pa	ge 8 of 9 Property Address:1	003 Weldin Circl		
Se	ller's Initials MAW S	eller's Initials MLVALL	Buyer's Initials	
-	Seller's Initials	Seller's Initials	Buyer's Initials	Buyer's Initials
	Seller has provided the information and belief, complete, true, and defects or problems with the profinvolved in the sale of this proper harmless any Real Estate Agent third-party reliance on the disclosure.	accurate. Seller has no knowled operty have been disclosed to, erty, other than those set forth involved in the sale of this pro-	This information is, to the edge, information, or oth or discussed with, any R in this report. Seller doe operty from any liability	ter reason to believe that any deal Estate Agent or Broker as hereby indemnify and hold incurred as a result of any
	and/or Cooperating Broker, if an a legally binding document. If n	y, is/are hereby authorized to	furnish this report to any	
	a legally bilding document. If h	or understood, an attorney sho	and be consumed.	
*	seller flat jobs	Date Below SEL	ĹER	Date_
	SELLER Marie Swing	Date Jufed SEL	LER	
	DateDate the cont	ents of this Report were last u	pdated:	*

ACKNOWLEDGMENT OF BUYER

Buyer is relying upon the above report, and statements within the Agreement of Sale, as the representation of the condition of the property, and is not relying upon any other information about the property. Buyer has carefully inspected the property and Buyer acknowledges that Agents are not experts at detecting or repairing physical defects in property. Buyer acknowledges Seller has completed this form based upon their knowledge of the

property. Buyer understands there may be areas of the property of which Seller has no knowledge and this report does not encompass those areas. Unless stated otherwise in my contract with Seller, the property is real estate being sold in its present condition, without warranties or guarantees of any kind by Seller or any Agent. Buyer has received and read a signed copy of this report. Buyer may negotiate in the Agreement of Sale for other professional advice and/or inspections of the property. Buyer understands there may be projects either planned or being undertaken by the State, County, or Local Municipality which may affect this property of which the Seller has no knowledge. Buyer further understands that it is Buyer's responsibility to contact the appropriate agencies to determine whether any such projects are planned or underway. If Buyer does not understand the impact of such project(s) on the property being purchased, Buyer should consult with an Attorney. Buyer understands that before signing an Agreement of Sale, Buyer may review the applicable Master Plan or Comprehensive Land Use Plan for the County and/or appropriate City or Town Plans showing planned land uses, zoning, roads, highways, locations, and nature of current or proposed parks and other public facilities. This is a legally binding document. If not understood, an attorney should be consulted. Date BUYER BUYER _____ Date ____ BUYER Page 9 of 9 Property Address: 1003 Weldin Circle



HighlandHS@Verizon.Net

(302) 994-1098 Office (302) 290-5530 Dan

(302) 442-0828 Ray

HIGHLAND HOME SERVICES, INC.

220 North Walnut Street Wilmington, DE 19804

DE Lic# 2008602324 NCC Lic# GC1179

1003 Weldin Circle Wilmington, DE 19803

August 17, 2024

The foundation was constructed in 1972 with Concrete Masonry Unit (CMU) block. Horizontal cracks and step cracks were evident on the front wall. These types of cracks and movement were caused by stress from Hydrostatic Pressure and reinforcement was recommended per report by Structures Unlimited, LLC dated August 6, 2024. We installed #5 steel rebar and grout inside the cores of the wall at recommended intervals to provide reinforcement. This procedure created fourteen steel and concrete pillars inside the hollow cores of the wall to ensure structural integrity.

All work was completed under New Castle County Permit 202410784, certified upon completion by Structures Unlimited, LLC., and Warranted by Highland Home Services, Inc.

Labor, Materials, Permit, Engineer Certification, Warranty - \$5,300.00

Highland Home Services, Inc. respects our customers' home and exceeds their expectations. We specialize in foundation structural repairs and are an EPA Lead Certified Contractor. All work is completed in a timely and professional manner. We are licensed, insured, and bonded.

Raymond Garrison Raymond Garrison HHS, Inc.



STRUCTURAL ENGINEERING & FORENSIC INVESTIGATIONS

2207 Concord Pike #297, Wilmington DE 19803

Office / Cell 302.540.7429

Mr. Christian Woolley 1003 Weldin Circle Wilmington, DE 19803 August 6, 2024

Structural Investigation Report 1003 Weldin Circle Wilmington, Delaware

Introduction: This report will summarize the results of my subject investigation that was performed at the request of your realtor on August 1, 2024. The purpose of the investigation was to assess concerns of cracks in the front foundation wall of the referenced property. An additional concern was raised in regard to a slope in the floor and also cracks on an interior wall. For the record, the two-story house is documented as being built in 1972.

Investigation: The front foundation wall of concern is constructed of 8" hollow concrete masonry units (cmu) up to the underside of floor joists. The 1st floor joist span perpendicular to the foundation wall of concern, this wall is termed 'load bearing'. The exterior face of the house is brick along the front and vinyl siding on the remaining sides with the main wall construction most likely that of 2x6 stud framing. The basement walls extend approximately 7'-9" up from the foundation with approximately all but 8" of that being below finish grade (ground level) along the front.

There is horizontal cracking that has occurred in the front wall. A horizontal crack is occurring along the 4th courses down from the top along the front wall of concern. See photograph #4. The crack is approximately 1/8th of an inch wide. Steps will need to be taken to strengthen and repair this rear foundation wall.

Along the right-side of the front foundation wall is a stair-step vertical crack. The wall appears to have a black waterproof coating. See photograph #1. The stair step crack has connected with a horizontal crack. Some internal re-bar will be required to 'sew' the masonry units together along with strengthening the wall due to horizontal cracking.

The floors have settled since they were first installed. The 2x12s that are viewable in the basement that frame the 1st floor have a lumber stamp. The lumber stamp denotes that the wood is a number #1 grade but was not kiln-dried. The stamp shows a "S-GRN" which means it was green lumber. See photograph #3. Some of the members measured less than 11" tall.

The hardwood floors have rolls and dips. This is common for floors that are framed with green lumber. A corner wall has noticeable separation and has dropped. See photograph #2. I was not able to connect this movement with a structural issue but most likely defined as a chronic crack area.

1003 Weldin Circle August 6, 2024

Problem Assessment: Unfortunately, the basement foundation walls were not initially built to code. The maximum unbalance height of fill against such a foundation wall that was allowed by code and standard practices back when this house was built was 4 feet (and still is). The backfill height in this situation is in the area of 7'-0" or more along the front.

By analysis (see attached), the maximum tensile stress that's developed in the wall under the aforementioned conditions is in the order of 138 pounds per square inch (psi) while the allowable stress for the concrete masonry construction involved is only 23 psi.

As shown in the calculations attached, the wall was initially beyond its limitations and with the additional lateral forces from expansion of the clay in the soil and higher hydrostatic pressure, and weight of the concrete porch slab the wall simply buckled from the force. Provisions will need to be taken to counter act the tendency for the basement wall to further move laterally inward and possibly collapse.

The vertical cracks in the cmu foundation wall are classic signs of differential settlement. These types of cracks are quite common for foundation walls that are situated above expansive clays. Furthermore, foundation walls lose continuity at openings and corners. These areas are more prone to cracking due to the natural shifting that occurs under the footing system. Such crack widths will vary with variations in ground temperature and moisture content; therefore, repointing the crack would fill the crack but due to constant movement in the ground the cracks might re-surface. Installing rod and grout into one or two of the cores will halt and 'sew' the cracked courses together.

The house has shrunk and in this case, the floor and wall conditions were exacerbated by the fact that the lumber used in the framing process most likely was "S-GRN" seasoning rating which means that the moisture content in the lumber was more than 19% when installed.

A higher moisture content tends to cause the lumber to shrink under its own weight and even more at load bearing area of the floors and roof. However, most of the shrinkage will occur in the first couple of years of the house and will diminish in later years. Having a joist shrink and the next one over does not is typical and creates a roll or drop along sections of the floor.

Cosmetic elements like brick that are actually a veneer and will not shrink; so, any elements that share the same space with both the wood framing and the non-movable sections will be greatly affected. See the attached article called "Framing Details for Wood Shrinkage". This article will not help what has happened to this date but will only clarify the situation. The wood studs are supported by the floor joists. The house framing settled and the brick veneer is push down and bows outwards. Some areas will see continuous cracking at the same location that is referred to as a 'Chronic Cracking', see attached articles.

Conclusion & Corrective Recommendations: Patching or sealing the crack on the inside face does not provide any resistance to the lateral forces that created the cracking. Ultimately, the horizontally cracked sections of the foundation walls will continue to move in and out during the different seasons due to swelling and contracting of the clayey soils and ultimately the cause the masonry units to fail further.

1003 Weldin Circle August 6, 2024

Currently the mortar bond between layers (courses) of block is broken horizontally and simply the weight of the wall above is pushing down to create dry friction. Once the wall bends inwards sufficiently, there are less of the two surfaces mating and therefore less friction; at that point, the wall will fail. Installing steel rods and grout inside the cores calculate to be sufficient in strength and will bring the wall of concern up to code. The following corrective recommendation is offered for your consideration:

Front Foundation Wall Repair:

• Reinforce the front foundation wall per "In-Wall Reinforcement" design attached. Install reinforcement with #5 vertical bars at 32" on center and fill the cmu core solid with grout as delineated in attached approximate layout sketch. See the basement layout sketch for desired locations of the wall reinforcement.

This report does not express or imply any warranty of the building involved but only addresses the conditions of the concerned portions of the house to the extent that these portions were readily accessible and observable.

The recommendations provided above are not intended to include or imply procedures needed to ensure construction phase safety. All construction must be done in compliance with the latest version of the occupational safety and health act (OSHA) requirements and all rules and regulations thereto appurtenant.


Thank you for considering us for this effort and please call me if there are any questions.


Respectfully Submitted, Structures Unlimited, LLC


Bjorn M. Haglid, P.E.

Delaware Professional Engineer #12118










1003 Weldin Circle Photographs


STRUCTURES UNLIMITED, LLC

STRUCTURAL ENGINEERING & FOREMSIC INVESTIGATIONS

101 Stone Tower Lane Wilmington, DE 19803

1003 Weldin Cir	cle, Wilmington DE
SHEET NO1	1
CALCULATED BY Bjorn	DATE 8/5/2024
CHECKED BY Bjorn	DATE 8/5/2024
N.T.S.	





p=wh, where w =equivalent-fluid weight of soil

$$W = \frac{wh^2}{2} = \frac{ph}{2}$$
; $C = \frac{2h}{3}$; $R = \frac{Wh}{3H}$; $R_1 = W - \frac{Wh}{3H}$

Maximum Shear: $V = R_1 = W \cdot \frac{Wh}{3H}$

Point of Maximum Moment:

Maximum Moment: $M = \frac{Wh}{3H} \left[h_1 + \frac{2h}{3H} \sqrt{\frac{h}{3H}} \right]$

		1 1 1		WALL WEIGHT (PSF)			FACE SHELL BEDDING		
HOLLOW 2-CORE	NOMINAL THICKNESS (IN)	NET AREA (IN*/FT)	NET VOLUME (IN³/FT³)	80	100 (BLOCK DE	120 NSITY PCF)	140	SECTION MODULUS (IN ³ /FT)	MOMENT OF INERTIA (IN*/FT)
CMU PHYSICAL	4	21.6	314	16	22	27	31	21.0	38.0
	6	32.2	388	21	26	31	36	46.3	130.3
DATA	_8	41.5	481	28	34	40	47	81.0	308.7
(ASTM-C-90)	10	50.4	592	34	42	49	57	117.8	566.7
(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	12	57.8	674	38	47	56	84	159.9	929.4

ALLOWABLE STRESSES IN NONREINFORCED CONCRETE MASONRY

Description	Allowable Stresses, psi ^a		
	Inspected	Not Inspected	
Tension in Flexure:			
Normal to bed joints'			
Type M or S Mortar,			
Hollow Units	23	11.5	
Solid Units	39	19.5	
Type N Mortar,			
Hollow Units	16	8	
Solid Units	27	13.5	
Parallel to bed joints*			
Type M or S Mortar,			
Hollow Units	46	23	
Solid Units	78	39	
Type N Mortar,			
Hollow Units	32	16	
Solid Units	54	27	
Shear			
Type M or S Mortar	34	17	
Type N Mortar	23	11.5	
Type 14 WOLGE	20	11,5	

¹ Direction of stress is normal to bed joints — vertically in normal mesonry construction.

$$h := 7.08 \text{ ft}$$
 $h1 := 0.67 \text{ H} \equiv 7.75 \text{ } \omega := 40 \text{ pcf}$

$$P := h \cdot \omega$$
 $P = 283.2$ psf

$$w := \frac{P \cdot h}{2} \qquad w = 1003 \quad \text{lbs/ft}$$

Moment

$$M := \frac{(w \cdot h)}{3 \cdot H} \cdot \left[h1 + \frac{(2 \cdot h)}{3} \cdot \sqrt{\frac{h}{3 \cdot H}} \right] \qquad M = 1000 \quad \text{ft lbs}$$

 $Mf := M \cdot 12$

Max Tensile Stress

Mf = 11996 in*lbs

$$Ft := \frac{425}{41.5} - \frac{Mf}{81.0}$$
 | | Ft | = 138 psi < 23 psi = no good


Necessary reinforcement steel = As

As = Mf/(fs*j*d) As :=
$$\frac{Mf}{24000.8865.125}$$
 As = 0.110 in²/ft

Use (1)#5 @ 32" o/c (every fourth course) = $0.115 \text{ in}^2/\text{ft}$

Direction of stress is parallel to bed joints — horizontally in normal masonry construction,

³ Net mortar bedded area,




STRUCTURES UNLIMITED LLC STRUCTURAL ENGINEERS

2207 Concord Pike #297 - Wilmington, DE 19803 (302) 540-7429

SCALE:	CHECKED BY:	CALCULATED BY: Bjorn Haglid P.E.	SHEET NO_	лов:1
	BY:	D BY:		003 1
½"=1'-0'	Bjorn	Bjorn		Weldin (
0,"	Bjorn Haglid P.E.	Haglid		Circle -
	P.E	P.E.		- Wilmir
	DATE:	DATE:	OF.	1003 Weldin Circle — Wilmington, DE
	DATE: 8/5/2024	_ DATE: 8/5/2024	2	m

SECTION 'A'



SPECIFICATIONS:

DIVISION 3: CONCRETE WORK:

CONCRETE: CONCRETE FOR FILLING MASONRY CORES SHALL BE PEA GRAVEL AGGREGATE CONCRETE HAVING A 6-INCH SLUMP AND PROPORTIONED TO OBTAIN CERTIFIED 3000 PSI 28 DAY COMPRESSIVE STRENGTH PER ASTM C150.

REBAR: ALL REINFORCING BARS SHALL BE NEW, DEFORMED BILLET STEEL BARS CONFORMING TO ASTM A615, GRADE 60.

SETTING: SETTING OF REBAR TO BE IN ACCORDANCE TO THE APPLICABLE REQUIREMENTS OF ACI 301, "SPECIFICATIONS FOR STRUCTURAL CONCRETE FOR BUILDINGS".

DIVISION 4: MASONRY

MORTAR: ALL MORTAR SHALL BE TYPE "M" ONLY AND MIXED IN CONFORMANCE WITH ASTM C270.

REPOINTING: FRACTURED MORTAR JOINTS REMAINING AT THE COMPLETION OF ANY NEW CONSTRUCTION SHALL BE CUT OUT AND REPOINTED.

TEMPORARY FORM PUNCH OUTS TO GROUT FULL HEIGHT OF CORES & PARGE FULL FACE OF WALL FOLLOWING THE REPOINTING OF FRACTURED MORTAR JOINTS & SETTING OF CONC. FILL.

TYP. IN-WALL REINF. SECTION

STRUCTURES UNLIMITED LLC STRUCTURAL ENGINEERS

2207 Concord Pike, #297 - Wilmington, DE 19803 (302) 540-7429

SHEET NO. 2	OF.	2
CALCULATED BY: Bjorn Haglid	DATE:	DATE: 8/5/2024
CHECKED BY: Bjorn Haglid, P.E. DATE: 8/5/2024	P.E. DATE:	8/5/2024
SCALE: N.T.S.		

Strengthening block basements with cast-in-place concrete

When unreinforced hollow-core block basement walls crack or deflect inward, the usual remedy has been to replace them or to bolster the inside of the wall with heavy steel members. Now, however, a patented engineered system is available to reinforce the hollow cores with cast-in-place concrete and vertical rebars, reportedly mak-




Deflection and cracking such as this in unreinforced concrete block basement walls can now be repaired by a process of placing reinforcement and concrete in the hollow cores of the masonry.

ing the failing block walls stronger than when they were new. The method is said to work for walls up to 5 inches out of plumb. An average residential installation takes 3 to 4 days and is done by a threeman crew inside the basement.

Select points for reinforced columns

The first step is to determine the number of "points" (locations) along the wall where reinforced concrete columns will be installed. Points will be no more than 4 feet



Openings are cut into the cells of distressed block walls, at points no farther than 4 feet apart. After reinforcement has been placed in the cells, 3000-psi concrete is used to complete the column-stiffener for the masonry wall.


apart. Working in the basement, the crew then makes a 3- to 4-inch-wide opening in the cells of the block at each predetermined point. This opening extends from near the top to mid-height of the wall (see drawing). The cells of the block are then cleaned out down to the footing through a hole made in the wall at the very bottom of each point.

Insert bars at each point

Two reinforcing bars of suitable diameter and grade of steel are inserted at each point. The rods are tied together and extend from the top of the footing to the top of the wall. A threaded rod is then inserted into the top of the cutaway wall opening and run up through a drilled hole in the sill plate where it is fastened with a nut. The bottom half of this threaded rod laps the top reinforcing rod and is tied to it. Next, metal anchors are installed which securely fasten the joists and sill plate together as shown in the drawing.

Concrete placed in open cells

Form boards are then placed over the open cells and 3000 psi concrete is poured into the cells, encasing the reinforcement, until each point is completely full. With the use of water reducing agents, the form boards can be removed early enough so that the surface of the concrete can be leveled and roughened to resem-



Metal anchor is installed to securely tie the floor joist and sill plate together.

ble the texture of adjacent blocks. Joints are tooled into the new concrete to present a continuous joint appearance. Also, the loose mortar remaining in cracked joints is removed and new mortar is applied.

After two days of curing, the exposed portion of the threaded rod is tightened against the top of the sill plate to complete the wall strengthening process. Engineering calculations show that this combination of metal plates, anchoring bolts and reinforced concrete column construction, all tied together, increases strength enough that added fill may be placed outside the basement walls to improve drainage.

Warranty and licensing


Following construction work, each field installation is inspected by a local registered engineer to verify compliance with specifications and local code. Homeowners are given a 5-year conditional warranty against further cracking from lateral movement.

The patented system is now being offered on a license basis to qualified concrete contractors.

Acknowledgement

Information presented here was abstracted from a longer article written by Willard S. Norton, a Kansas City, Missouri engineer who developed the repair method.

FRAMING DETAILS FOR WOOD SHRINKAGE



Early in my carpentry career, I was asked to remove all the trim from the third-floor hallway

of a 140-year-old house we were renovating. All the baseboards in the hallway were touching the floor, except for one piece, which was 2 inches off the floor. It didn't make sense until I had removed the baseboard in the hallway. While most of the walls consisted of plaster and lath over studs, the wall

behind the base that didn't touch the floor was plaster over a brick chimney. When the house was originally built, the air-dried framing lumber dried and shrank, and all of the third floor dropped except for that one piece of baseboard fastened to the chimney.

Today, most builders frame with kiln-dried stock. But if you think that means you don't have to be concerned

about wood shrinkage, think again: Kiln-dried lumber will definitely shrink. How much depends on its moisture content at the time of installation (see "Calculating Shrinkage"). And as the lumber shrinks, it tends to twist and bow, causing humps and nail pops in walls, and bumpy, squeaky, out-of-level floors.

To avoid wavy floors and binding doors, use quality framing materials and details that allow for lumber shrinkage

Understanding Wood Shrinkage

Moisture affects wood the same way it affects a sponge. If you take a sopping-wet sponge and wring it out, you'll remove some of the water, though not

Calculating Shrinkage

Because wood shrinks and swells at a predictable rate, it's possible to calculate how much a building, or any part of a building, will shrink as it dries. Let's say we want to find out how much a kiln-dried Hem-Fir 2x12 at 19% MC will shrink if it's dried to 8% MC. We need something called the coefficient for dimensional change — the shrinkage coefficient — which expresses the percentage change in the size of a piece of wood for each percentage change in its MC. Although different wood species have slightly different shrinkage coefficients, an average number for flat-sawn framing lumber is .0025. You can safely use this to calculate the shrinkage for average 2-by stock.

With that in mind we can use the following formula:


Shrinkage (or swelling) = Width of wood x change in MC x Shrinkage Coefficient

So a typical 2x12 will shrink about $^5/16$ inch as it moves from 19% MC to 8% MC (11.25 inches x (19-8) x .0025). A 2x6 would shrink half as much (see chart, below). The formula can also be used to calculate how much wood swells as MC increases.

Predicted Shrinkage of Dimension Lumber

Lumber Size	Actual Width	Width @ 19% MC (at Delivery)	Width @ 11% MC (Humid Climates)	Width@ 8% MC (Average Climates)	Width @ 6% MC (Arid Climates)
2x4	3 1/2"	31/2"	37/16"	33/8"	33/8"
2x6	51/2"	5 ¹ /2"	53/8"	5 ⁵ /16"	5 ⁵ / ₁₆ "
2x8	71/4"	71/4"	71/8"	71/16"	7"
2x10	9 1/4"	91/4"	91/16"	9"	8 ¹⁵ /16"
2x12	111/4"	11 ¹ /4"	11"	10 15/16"	107/8"

Note: Framing lumber shrinks primarily across its width; shrinkage along the lumber length is insignificant. Actual shrinkage varies depending on the lumber's moisture content when delivered and the area's climate.



enough to change the sponge's size. But if you let the damp sponge dry out, it will shrink. And if you wet the dry sponge, it will swell back up until it reaches the point where it can't absorb any more water and can't get any larger.

In a piece of wood, moisture resides both in the cell cavities and in the cell walls. Green wood is like a sopping-wet sponge: As it dries, the moisture in the cavities is the first to go. But, as with the sponge, this doesn't cause the wood to shrink. The point at which there is moisture in cell walls, but not in cell cavities is called the *fiber saturation point*. Below this level, the wood (like the sponge) will shrink as it dries and swell as it absorbs moisture.

The amount of moisture in a piece of wood is referred to as its moisture content (MC). Moisture content is the ratio of the weight of the moisture in a piece of wood to the weight of the piece of wood if all of the moisture were removed.

Because the water in a piece of green wood can easily outweigh the wood fiber, wood can have a moisture content of more than 100%. The fiber saturation point of most wood species is 25% to 30% MC; kiln-dried framing lumber is supposed to have no more than 19% MC. Since this is well below the fiber saturation point, the wood will swell and shrink with changes in moisture content.

Wood stored at a constant humidity eventually reaches a stable MC, called the *equilibrium moisture content*. For most of the U.S., the equilibrium MC of wood that's inside a building is around 8%. In arid climates like Arizona, it's closer to 6%, while in moist climates like Florida, it's closer to 11%. This means that a piece of kiln-dried lumber will lose 8% to 13% MC after installation.

Start With Dry Lumber

Kiln-dried framing lumber is stamped KD or S-DRY (surfaced dry). Lumber stamped S-GRN (surfaced green) has not been kiln dried. Its MC was higher than 19% at the time it was milled — probably a lot higher. Avoid S-GRN lumber anywhere you're concerned about shrinkage. Also be aware that anything larger than a 4x4 isn't available in KD. The outside of these timbers may be somewhat dry, but assume that the inside is pretty green. When using a large solid beam, like a 6x6 or a 6x10, keep in mind that it will shrink a lot more than a comparable built-up beam made from kiln-dried stock.

You can minimize the effects of moisture swings by ensuring that all your framing lumber has the same MC. This means storing it up off the ground and protecting it from sun and rain with a tarp. It's just as bad to let the joists on top of the lift dry out in the sun as it is to let the bottom ones soak in a puddle. The idea is to make sure that all of the members in a given




Figure 1. Watch out for situations where wood shrinkage can compound to create noticeable problems. In the house shown here, the two builtup 2x12 girders will cause the center bearing wall to shrink much more than the exterior walls. This will result in a 1/2-inch drop at the second floor level enough to cause nail pops and cracks in the finishes. Using a steel I-beam in the basement and engineered lumber or flush framing at the second floor will alleviate the problem.

component — all of the joists in a floor, for instance — shrink the same amount.

Dry the Frame

Studs that are straight at 19% MC can do a lot of twisting and bowing as they dry to 8%. The U.S. Forest Products Lab (FPL) recommends that a frame be within 5% of its final moisture content before walls and ceilings are closed in. At the company I work for, we try to dry the frame to 10% or 12% MC before installing drywall or plaster. This gives us a chance to fix or replace any pieces that bow.

In cold weather, drying the frame may require some heat. A few winters back, I used a moisture meter to record how long it took the frame of a house I was working on to dry out. It was cold, but the humidity was low and the house was weathertight. After three weeks, most of the frame was stuck at

15%. We then set up an old gas furnace as a temporary heater. A week and half later, everything had dried to around 10%. Of course, it's not cheap to use heat to dry out a house. But if you're doing a high-end job, it beats coming back later to repair drywall, tile, and trim. And the heat doesn't have to be all that high. The FPL says that you need only keep the inside of the building 10 to 15 degrees warmer than the outside.

Pay Attention to Framing Details

Even if you purchase high-quality framing lumber and protect it after it arrives, you still won't be able to prevent the wood from shrinking altogether. But if you use framing details that allow for the shrinkage, you will avoid most of the problems that can occur when the frame shrinks.

Problems occur when one side of the building has considerably more headers and plates than the other side, when there's an improper connection to masonry, or when solid lumber is mixed with steel or engineered lumber without compensating for the materials' different shrinkage rates. The symptoms include sloping floors, and lumps and dips in floors and walls. Although this sounds complicated, it's fairly easy to design a frame that will shrink evenly.

Avoid Lopsided Shrinkage

It's important to recognize situations when a structure will shrink unevenly. Look at the example in Figure 1. Here, the first-floor joists are supported by a built-up 2x12 girder. The upstairs features an open floor plan, with the second-floor joists also resting on a 2x12 girder.

The problem with this configuration is that the two girders may shrink as much as ⁵/16 inch each as the lumber






Figure 2. Floor joists laid flush with the top of engineered or steel beams will create a bump in the floor when they shrink (top drawing, left). In these situations, install the joists ¹/₂ inch high to accommodate the anticipated shrinkage (bottom drawing, left). Where I-joists meet an engineered lumber beam (above), you can install them flush since shrinkage is not an issue with I-joists.

dries from 19% moisture content to 8%. This is much more than the shrinkage that would occur in the exterior walls. The first-story ceiling and the second-story floor will then drop by ½ inch or more, wreaking havoc with the drywall finish and possibly leaving noticeable dips in the floor.

The solution is to use girder material that doesn't shrink — either steel or LVL — or to flush-frame the girders.

Whenever you're flush-framing a floor system where solid wood joists meet an

engineered lumber or steel beam, don't set the tops of the joists exactly even with the top of the beam (Figure 2). Otherwise, when the joists shrink, they'll leave a bump in the floor. When I'm faced with this situation, I drop the beam approximately 1/2 inch in relation to the joists, so the joists can shrink without the top of the beam contacting the subfloor.

Foundation Details

Some designs call for the first-floor joists to bear on an interior foundation

ledge, as in Figure 3. The problem here is that when the joists shrink, the ends pull away from the subfloor, leaving a slope at the exterior wall. I once installed a refrigerator in a kitchen that was framed this way; the floor sloped so badly that I couldn't level the refrigerator with the leveling feet.

A better detail is to keep the subfloor off of the sill plate. When the floor joists shrink, the subfloor will move with them. When installing a wood floor, you can prevent a gap from opening beneath the baseboard by installing the flooring after the baseboard and using a shoe mold that's attached to the floor.

Where Wood Meets Masonry

If the framing isn't dry when a concrete hearth is poured, the framing will shrink so that the hardwood floor surface ends up slightly below the hearth. Because hearths are usually set late in the job, after the framing has had time to dry, this is seldom a problem. But if the hearth is set earlier — or if cold weather prevents the frame from drying — you should anticipate shrinkage and set the hearth a bit lower.

David Frane, of Wakefield, Mass., is a contributing editor to the Journal of Light Construction and an associate editor with Tools of the Trade.




Figure 3. Subflooring that is installed underneath the exterior wall framing (left) will cause a slope as the floor joists shrink. Where floor joists bear on a foundation ledge, the subflooring should stop short of the exterior wall (right). This allows the subfloor to move with the joists as they shrink.

Strengthening block basements with cast-in-place concrete

When unreinforced hollow-core block basement walls crack or deflect inward, the usual remedy has been to replace them or to bolster the inside of the wall with heavy steel members. Now, however, a patented engineered system is available to reinforce the hollow cores with cast-in-place concrete and vertical rebars, reportedly mak-




Deflection and cracking such as this in unreinforced concrete block basement walls can now be repaired by a process of placing reinforcement and concrete in the hollow cores of the masonry.

ing the failing block walls stronger than when they were new. The method is said to work for walls up to 5 inches out of plumb. An average residential installation takes 3 to 4 days and is done by a threeman crew inside the basement.

Select points for reinforced columns

The first step is to determine the number of "points" (locations) along the wall where reinforced concrete columns will be installed. Points will be no more than 4 feet



Openings are cut into the cells of distressed block walls, at points no farther than 4 feet apart. After reinforcement has been placed in the cells, 3000-psi concrete is used to complete the column-stiffener for the masonry wall.


apart. Working in the basement, the crew then makes a 3- to 4-inch-wide opening in the cells of the block at each predetermined point. This opening extends from near the top to mid-height of the wall (see drawing). The cells of the block are then cleaned out down to the footing through a hole made in the wall at the very bottom of each point.

Insert bars at each point

Two reinforcing bars of suitable diameter and grade of steel are inserted at each point. The rods are tied together and extend from the top of the footing to the top of the wall. A threaded rod is then inserted into the top of the cutaway wall opening and run up through a drilled hole in the sill plate where it is fastened with a nut. The bottom half of this threaded rod laps the top reinforcing rod and is tied to it. Next, metal anchors are installed which securely fasten the joists and sill plate together as shown in the drawing.

Concrete placed in open cells

Form boards are then placed over the open cells and 3000 psi concrete is poured into the cells, encasing the reinforcement, until each point is completely full. With the use of water reducing agents, the form boards can be removed early enough so that the surface of the concrete can be leveled and roughened to resem-



Metal anchor is installed to securely tie the floor joist and sill plate together.

ble the texture of adjacent blocks. Joints are tooled into the new concrete to present a continuous joint appearance. Also, the loose mortar remaining in cracked joints is removed and new mortar is applied.

After two days of curing, the exposed portion of the threaded rod is tightened against the top of the sill plate to complete the wall strengthening process. Engineering calculations show that this combination of metal plates, anchoring bolts and reinforced concrete column construction, all tied together, increases strength enough that added fill may be placed outside the basement walls to improve drainage.

Warranty and licensing

Following construction work, each field installation is inspected by a local registered engineer to verify compliance with specifications and local code. Homeowners are given a 5-year conditional warranty against further cracking from lateral movement.

The patented system is now being offered on a license basis to qualified concrete contractors.

Acknowledgement

Information presented here was abstracted from a longer article written by Willard S. Norton, a Kansas City, Missouri engineer who developed the repair method.

LIMITED LIABILITY WARRANTY

under a New Castle County Permit and Certified by a Professional Engineer. We warrant that the runoff, your foundation should support your home for a lifetime. We are available to you for consult Your foundation has been reinforced by Highland Home Services, Inc. All work was completed that will result in failure of the foundation to structurally support the home. This warranty is limited maintenance, operation of heavy equipment near the foundation, and other types of neglect can lead to foundation compromise. With proper care, maintenance of gutters, downspouts, and rainwater at any time if you have questions, concerns, or need advice about your foundation. We appreciate portion of the foundation that was reinforced by us will not experience any significant movement to a period of ten years and liability is limited to the original cost of labor and materials. you trusting your repair to Highland Home Services, Inc.

Daniel A. Burroughs

Daniel A. Burroughs President, HHS, Inc.

Property Address: 1003 Weldin Circle
Date: August 17, 2024

Coverage: \$4,950.00

Highland Home Services, Inc. 220 North Walnut Street Wilmington, DE 19804

Disclosure of Information on Lead-Based Paint and Lead-Based Paint Hazards Sale of Residential Property

Property: 1003 Weldin Circle, Wilmington, D	DE 19803	N Seller's Name:	larc A and Mavis L Woolley			
Property: 1003 Weldin Circle, Wilmington, D		Seller S Ivallic.				
Seller Instructions: Check the box indicate the age of your property and initial. If you checked either box 1 or 3, continue to complete the Seller's Disclosure section be and sign this form at the bottom. If you checked box 2, sign below to complete this form.	low 1/1 /1/a	2. was constructions to	Was Constructed: ted prior to January 1, 1978 ted after January 1, 1978 to when constructed			
Lead Warning Statement - Every Purchaser that such property may present exposure to le poisoning in very young children may product behavioral problems, and impaired memory. real property is required to provide the Purchaser of Seller's possession and notify the Purchaser of hazards is recommended prior to purchase.	and from lead-based paint the be permanent neurological of Lead poisoning also poses a saser with any information of	at may place young children at risk of o lamage, including learning disabilities, a particular risk to pregnant women. Th n lead-based paint hazards from risk as	developing lead poisoning. Lead reduced intelligence quotient, e Seller of any interest in residential sessments or inspections in the			
Seller's Disclosure – Unless box 2 is checked initialing in each of these two sections (if more than one owner, all owners).	ners must select and initial)					
(a) Presence of lead-based paint an	d/or lead-based paint hazar	ds (CHECK ONE BOX BELOW AND	INITIAL):			
Select answer and initial Know	n lead-based paint and/or lo	ead-based paint hazards are present in the	he housing. (explain)			
		pased paint and/or lead-based paint haz	ards in the housing.			
(b) Records and reports available to	the Seller. (CHECK ONE	BOX AND INITIAL):				
Select answer and initial						
Seller	has no reports or records p	ertaining to lead-based paint and/or lea	d-based paint hazards in the housing.			
Purchaser's Acknowledgement - Unless bo						
	r(s) has read the Lead Warn					
()	` '	all information listed above.				
		llet Protect Your Family From Lead In	Your Home.			
	r(s) has (check one below):					
		or mutually agreed upon period) to cond d-based paint and/or lead-based paint h				
☐ Waive	-	ct a risk assessment or inspection for th				
Agent's Acknowledgement – Initial below						
(g) The Listi	ng Agent has informed the of his/her responsibility to	Seller of the Seller's obligation under a ensure compliance.	42 U.S.C. 4852(d), and the Seller			
Certification of Accuracy – The following prinformation provided by the signatory is true		A.				
Seller Lew	7/2/24 Date	Seller L WOO	1/9 7/2/24 Date			
Purchaser 0	Date	Purchaser	Date			
Agent	Date	Agent	Date			



RADON DISCLOSURE

Required by Chapter 25, Title 6, Section 2572A of the Delaware Code

Property	Address: 1003 Weldin Circle, Wilmington, DE 19803	_
Delaware dwelling r	Disclosure I law requires that the seller of any interest in residential real property that includes a must provide the buyer with any information about any known radon. Sellers also must any tests or inspections for radon in the seller's possession.	
The selle	r(s) must answer the following questions and provide the required information:	
1. /	Are you aware of the presence of radon in the property identified above? ☐ Yes ☑No	
	Are you aware of any radon tests or inspections that have been performed on the property identified above? ☐Yes ☐No	
	If you responded "yes" to Question 2 above, have you provided the buyer(s) with copies of all radon tests and/or inspection reports in your possession? \square Yes \square No	
4.	Identify each report referred to in Question 3, including the date of each report:	
Seller -	g this form, the seller(s) acknowledge(s) the following: we have been informed of my/our obligation and am/are aware of my/our responsibility to omply with Delaware law regarding radon disclosure, as provided in Title 6, Chapter 25, ection 2572A of the Delaware Code. Acknowledgement Date Date	19
dwelling n	law requires that every buyer of any interest in residential real property that includes a must be notified that the property may present the potential for exposure to radon.	
	g this form, the buyer(s) acknowledge(s) the following:	
	we have received the Radon Rights, Risks and Remedy for Home Buyer document, which describes the potential hazards of exposure to radon, testing for radon and remediation.	ĺ
2. I	/we have the option to have the property identified above tested for radon.	
	/we have received copies of all radon tests and/or inspection reports identified in Item 4 of the Seller's Disclosure above.	
Buyer	Date Buyer Date	
	Form Approved by Delaware Real Estate Commission September 12, 2007	7

SCHOOL FEEDER PATTERN

Brandywine School District 2024/2025 School Year

Lombardy Elementary School

Grades: KN-05

Address: 412 Foulk Road

City: Wilmington Zip Code: 19803

Springer Middle School

Grades: 06-08

Address: 2220 Shipley Road

City: Wilmington Zip Code: 19803

Brandywine High School

Grades: 09-12

Address: 1400 Foulk Road

City: Wilmington Zip Code: 19803